

US EPA ARCHIVE DOCUMENT

UNIT LOG	1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 03/19/2012	3. Time Prepared 1600
4. Unit Name/Designators Situation Unit	5. Unit Leader (Name and Position) Melinda Luetke, Planning Section Chief		6. Operational Period 0700, 03/15/12 – 0700, 03/22/12
7. Personnel Roster Assigned			
Name		ICS Position	Home Base
Matthew Haak		Situation Unit Leader	Houston, Texas
8. Activity Log			
Time	Major Events		
11:00	<p>Overflight Operational status:</p> <ul style="list-style-type: none"> Observed demobilization of the staging area at the farmhouse on Division Drive. Observation restoration of staging area off 16 Mile Road. Timber mat staged in area just west of 15-1/2 Mile Road. Talmadge Creek near MP1.75, sheen observed. Confluence, no sheen or turbidity issues observed. Scrape activities resumed at OB8.97. Scrape area at OB9.10 restored. Scrape underway at OB 10.37 RDB. MP10.37 LDB overbank sheen observed. Mill Pond, observed public fishing. MP28.25 Oxbow, observed public fishing. 		
	Additional observations: None		
15:00	Return to ICP.		
9. Prepared by (Name and Position) Matthew Haak, Situation Unit Leader, USEPA-START			